## PACIFIC PILOTAGE AUTHORITY

1000 – 1130 West Pender Street Vancouver, B.C V6E A4A



## **NOTICE TO INDUSTRY**

**Date Issued:** March 13, 2008 Notice Number: 01/2008

**Subject:** Passing Arrangements Seymour Narrows and First Narrows

**Geographic Area:** English Bay and Seymour Narrows

**Details:** This notice is as a result of concerns raised by the cruise industry during the 2007 season.

## Guideline:

(A) For Northbound transits the following guidelines are recommended:

- (1) Whenever possible, in normal circumstances, avoid overtaking North of Kuhushan Point for a predetermined line-up position (as indicated by the Seymour Narrows Guidelines) for Seymour Narrows.
- (2) Whenever possible, in normal circumstances, avoid overtaking North of Boat Harbour light, for a transit of Blackney Pass.
- (B) For Southbound Transits the following guideline is recommended:
  - (1) Whenever possible, under normal circumstances, avoid overtaking East of Point Atkinson for the prearranged line-up for First Narrows' transits.

If there are any queries, concerns please feel free to contact me at <a href="marineops@ppa.gc.ca">marineops@ppa.gc.ca</a> or by telephone at 604-666-6771 not later than Thursday March 20th.

Kevin Obermeyer President and CEO

If there are any questions or concerns regarding this notice please contact the Director, Marine Operations at (604) 666-6771 or via email to marineops@ppa.gc.ca or via mail to the above address.